

Ersatzteilliste für den Bing-Vergaser 81/8/101

Bing-Nr		Bezeichnung	tenblatt	E-Preis	Anzahl	Preis
44-054/42-01		Düse 42 ohne Sieb	1	7,00 €		- €
44-054/43-01		Düse 43 ohne Sieb	1	6,50 €		- €
57-711-02		Sieb für Düse		2,50 €		- €
35-924-06		Schwimmer	3	11,00 €		- €
165-586-01		Dichtung für Schwimmerkammer	4	2,00 €		- €
130-630-07		Schwimmerkammer	5	7,00 €		- €
122-215-06		Gasschieber	7	4,00 €		- €
160-530-01		Feder (Gasschieber)	8	1,00 €		- €
126-552-03		Andruck-Platte	9	2,50 €		- €
149-299-01		Kerbstift	10	1,00 €		- €
157-615-07		Startschieber	11	4,00 €		- €
161-623-04		Sicherungsring	12	0,50 €		- €
160-157-04		Feder Starthebel	15	1,00 €		- €
161-686-02		Sicherungsscheibe	17	0,40 €		- €
26-541-14		Deckelplatte	18	13,00 €		- €
126-376-05		Starthebel	19	3,00 €		- €
161-129-01		Schenkelfeder Start.	24	1,50 €		- €
165-864-03		Dichthülse	28	0,25 €		- €
160-113-00		Feder (Membran)	29	1,00 €		- €
65-843-09		Membrane mit FB	30	18,00 €		- €
165-721-00		Gummidichtring	32	0,30 €		- €
165-587-01		Dichtung oben	33	1,50 €		- €
160-064-02		Feder (Kurzschluss)	38	0,25 €		- €
161-614-02		Sicherungsscheibe	21 / 25	0,40 €		- €
					Porto	
					Summe	- €

Herbert Freisen
 Bultkamp 5
 33611 Bielefeld
 Konto 15653140
 BLZ 48050161 Sparkasse Bielefeld

0521-8752578
 0171-2859850
h.freisen@gmx.de

www.hilfsmotor.eu